

PARTS LIST
GS1500CR

OPERATORS PRODUCED AFTER 10/29/68

<u>PART NO</u>	<u>DESCRIPTION</u>	<u>QUANTITY</u>
EC-1260	Engine Wisconsin VGLD	
G-4853	Skid Base Assembly	
I-33	Drive End Bell	
I-804	Adaptor Coupling (Engine)	
G-5225	Generator Support	
EE-1201	Start Contactor	1
G-4766-1	Armature Assembly	1
I-794	Coupling Hub	1
G-5279	Assembly Fan	1
S-4872	Coupling Disc	1
D-8	Bearing	1
G-4420	Brushholder Assembly	4
J-515	Brushholder Pins	2
H-918	Field Coil Assembly	Set of 4
J-314-1	Coil Shields	8
G-2547	Field Pole Assembly	Set of 4
EE-1950-1	Inductive Reactor	1
EE-969-1	Voltage Regulating Transformer	1
G-4862-2	Rectifier Assembly	1
EE-1951	Battery Charging Transformer	1
AM-100	Battery Charge Ammeter	1
EE-425	Fuse Holder	1
EE-441	Fuse-Battery Charge	1
EE-1608	Circuit Breaker-70Amp 2 Pole	1
EE-658	Terminal Strip - 3 Pole 90 Amp	1
EE-658.01	Terminal Strip Marker	1
EE-172	Run-Stop Switch	1
EE-174	Push Button Start Switch	1
EE-653	Terminal Strip - 8 Pole 10 Amp	1
EE-653.02	Terminal Strip Marker	1
EE-645	Terminal Strip - 2 Pole	1
EE-645.01	Terminal Strip Marker	1
EE-151	Hi-Lo Battery Charge Switch	1
R-107	Resistor-Low Battery Charge	1
R-12	Resistor-High Charge	1
Y-51	Brushes	8
G-3422	Brush Springs	8

WIRING DIAGRAM

Z-1932-2 C-5906-2

Before 10/29/68 F-4119

